DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-020666 Address: 333 Burma Road **Date Inspected:** 23-Jan-2010

City: Oakland, CA 94607

OSM Arrival Time: 1900 **Project Name:** SAS Superstructure **OSM Departure Time:** 700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: See Below **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

Summary of Items Observed: On this date Caltrans OSM Quality Assurance (QA) Inspector, Mike Hasler was present during the times noted above for observations relative to the work being performed.

OBG Segment Name: 5CE / Trial Assembly

This Caltrans QA inspector observed Shielded Metal Arc Welding (SMAW) in progress. Welder is identified as #058087 welding critical weld repair B-CWR-1075, CA024-002, 004 and 006 in the 2G position using welding procedure specification WPS 345-SMAW-2G(2F)-FCM-Repair-1. ZPMC QC inspectors are identified as Mr. Zhang Qiang and Certified Welding Inspector (CWI); Mr. Li Yang. The welding variables recorded by QC appeared to comply with the welding procedure specification (WPS).

OBG Segment Name: OBG 5AE-5BE, BP-D6 / Trial Assembly

This QA Inspector performed verification Ultrasonic Testing (UT) in accordance with ABF/CT Pattern "D" UT Procedure 001 Revision 1. The welds tested were scanned with Pattern 'D" only in locations were flush grinding was present. All rejectable Indications were recorded on a data sheet that ABF and Caltrans QA generated after performing a joint inspection. The members are identified as the Bottom plate splice weld at D6 for segment 5AE-5BP. The weld designations are as follows:

OBE5A-003

This Caltrans QA inspector performed UT inspection using the conventional scan pattern A, B, C, and "D" per ABF Verification Witness Request #01222010-1 Item 1, weld repair, 5AE-5BE BP-D6. QAMT/VT was not performed, due to the surface condition of the plate having coupling on it from ABF UT inspection. See Segment Splice NDT Tracking, dated 01-23-10 and Caltrans Ultrasonic Test Report (TL6027), dated 01-23-10 for

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

additional information.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

"As noted within the contents of this report."

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or 1500026784, who represents the Office of Structural Materials for remedial efforts please contact James Devey your project.

Inspected By:	Hasler,Mike	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer